

Fig. 1




Fig. 3




Fig. 2




Fig. 6

TENCOR INSTRUMENTS PROMETRIX UV-1250SE  
 TENCOR PRSE401






Fig. 4  
 (PRIOR ART)


**TENCOR INSTRUMENTS PROMETRIX UV-1250SE  
TENCOR PRSE401**




**Fig. 5**




**Fig. 7**




**Fig. 8**




**Fig. 9**




**Fig. 7a**




*Fig. 10a*




*Fig. 10b*




*Fig. 10c*




*Fig. 10d*



*Fig. 10e*



**Fig. 11**



**Fig. 12**